

May 29, 2009

The County of Grey
Human Resources Department
595 9th Avenue East
Owen Sound, Ontario N4K 3E3

Attn: Mrs. Geraldine Cole

**Re: Chatsworth Storage Shed – Building ID: GC03
Asbestos Audit**

Dear Mrs. Cole,

Abacon Environmental Consultants Inc. conducted an asbestos audit of the Storage Shed located at 317157 Hwy 10 in Chatsworth, Ontario. The purpose of the audit was to determine whether any asbestos-containing materials were present in the building.

The audit was conducted on March 2, 2009. The Shed is a small wooden structure clad with wood panels, and covered by an asphalt shingled roof. The roofing materials were not tested. No other suspect asbestos-containing materials were noted in the building.





No concealed spaces were observed within the building.

It is recommended that the roofing materials be tested prior to renovation or demolition work.

Please contact this office should you require more information.

Very truly yours,

Marek Jakubczyk, M.Eng.
Principal



LEGEND	
(25)	LOCATION NUMBERS
NAR	NO ACCESS TO ROOM
12	BULK SAMPLE
	INACCESSIBLE WALL SPACE
	INACCESSIBLE CEILING SPACE

LOCATIONS OF BULK SAMPLES AND INACCESSIBLE BUILDING SPACE

SITE PLAN

REVISIONS			
DRAWN BY	CP	SCALE	NTS
CH'D BY	MJ	DWGNo.	
DATE	MAY 25 2009	GC02,03-BLK-1	



FLOOR PLAN of CHATSWORTH SAMPLE TRAILER/SHED

BUILDING ID
GC02
GC03